Prepared By:
City of Charlotte Housing & Neighborhood Services
600 E. Trade Street
Charlotte, NC 28202
(704) 336-7600

Property Details		\$100m					
Address:	3529 Carlyle Dr (Addom)	(m	Owner:	Yvonr	ne Lindsay		
	Charlotte, NC 28208		Owner Phone:	Home	: (704) 392-5	495	
Structure Type:	Single Unit		Program(s):	Teste	d- NO LEAD		
Square Feet:	990			Safe I	Home FY 201	8	
Year Built:	1955						
Property Value:	68700						
Tax Parcel:	06109505						
Census Tract:							
Property Zone:	Council District 3						
Repair Category: 0	0.0 General Requirements						
<u>Description</u>				<u>Floor</u>	Room		<u>Exterior</u>
Permits Required					GENERAL	REQU	IIREMENET&Serior
The contractor is respo	onsible obtaining and paying for all perm	nits required	. Said permits s	hall incl	ude all items	in this	scope of work.
					•		
		Bid Cost	:				
			Base		Quantity		Total Cost
Dumpster					GENERAL	REQU	IIREMENEKSerior
	ired permits, place AS MANY roll-off du ol methods. Remove dumpster and rep trailers.						
		Bid Cost	:	Х	=	:	
			Base	· ·	Quantity		Total Cost
Portable Toilet					GENERAL	REQU	UREMENET Kerior
Provide temporary toile	et facilities from job start until approval o	of permanen	t facilities.				
		Bid Cost	•	_x		:	
			Base		Quantity		Total Cost

Repair Category: 02.0 Site Improvements

Description		<u> </u>	<u>loor</u>	Room	<u>Exterior</u>
Exterminate Termites				GENERAL R	EQUIREMENT Serior
Exterminate for termites, Drill and patch foundation and paver year guarantee with an optional yearly renewable warranty for			ninato	or must be licen	sed and provide a 1
	Bid Cost:		x	=	
		Base		Quantity	Total Cost
Repair Category: 06.0 Roof, Chimney, Gutters & Do	wnspouts				
Description		E	<u>loor</u>	Room	Exterior
Tear Off & Reroof Shingles (Health Homes)				EXTERIOR	Exterior
Remove and dispose of existing roofing, inspect and repair roof 30 year architectural shingles. Include ice and water shield at a necessary accessories. (13.3)					
	Did Cook		v	_	
	Bid Cost:		^		
	Bid Cost:	Base	^	Quantity	Total Cost
Repair Category: 08.0 Doors & Windows	BIG COST:	Base	0.000000	Quantity	Total Cost
Repair Category: 08.0 Doors & Windows Description	BIG COST:		oor	Quantity	Total Cost Exterior
	BIO COST:		oor		
Description	order and insta new extension seded. Repair a	<u>FI</u> ill new Energ jambs, casin ll areas distur	y Star g and bed b	Room EXTERIOR rated vinyl, dousill as needed, by removal and i	Exterior Exterior Ible glazed LOW- E prime and paint. Installation. This
Description Vinyl Window Dispose of window units and any security bars. Field measure, windows including half screens. Insulate rough opening. Install Exterior trim to be wrapped in PVC coated aluminum coil as ne installation is to include repairing any damaged header, framing	order and insta new extension seded. Repair a	El ill new Energ jambs, casin il areas distur g studs, jack	y Star g and bed b	Room EXTERIOR rated vinyl, dousill as needed, by removal and i	Exterior Exterior Ible glazed LOW- E prime and paint. Installation. This

Prehung Metal Door Entrance - KITCHEN DOOR

Remove existing door, frame and threshold. Install new Energy Star rated pre-hung exterior door. Insulate cavity. Install mortised dead bolt and lever handled door hardware keyed alike. Install wide peep sight. New casing and shoe molding will match existing. Apply primer and topcoat, this installation to include repairing any damaged header, door framing, to include wall framing, sub-floor, floor joists and sill.

	Bid Cost:		_x	=	
		Base		Quantity	Total Cost
Repair Category: 09.0 HVAC					
Description		<u> </u>	-loor	Room	Exterior
Replace Duct Work with Tape Repairs				GENERAL F	REQUIREMENTS erior
Replace all ductwork which has been taped / repaired.					
ing in the second se	Bid Cost:	Base	_x	==	Total Cost
Fan/Light Fixture- Energy Star Bathroom				BATHROOM	II- MASTER
	Bid Cost:		Х	=	
		Base		Quantity	Total Cost
Range Hood Exterior Vented - KITCHEN					
Range Hood Exterior Vented - KITCHEN Install an exterior ducted enameled range hood with integra cabinet with screws. Include metal vent and roof or wall ca					
Install an exterior ducted enameled range hood with integra		y, using #14	coppe	er Romex. Ow	
Install an exterior ducted enameled range hood with integra	ap/damper assemb	y, using #14	coppe _x	er Romex. Ow	ner's choice of color.
Install an exterior ducted enameled range hood with integra	ap/damper assemb	y, using #14	coppe _x	er Romex. Owi	ner's choice of color.
Install an exterior ducted enameled range hood with integra cabinet with screws. Include metal vent and roof or wall ca	ap/damper assemb	y, using #14 Base	coppe _x	er Romex. Own	ner's choice of color.
Install an exterior ducted enameled range hood with integra cabinet with screws. Include metal vent and roof or wall ca	ap/damper assemb	Base	X damp	er Romex. Own	ner's choice of color.

Repair Category: 10.0 Electrical

<u>Description</u>			<u>Floor</u>	Room	<u>Exterior</u>
Smoke Detector Hard Wired				GENERAL R	EQUIREMENEKSerior
Install in 2 bedroom and middle-rear den. Install UL approved, interconnected, ceiling mounted smol battery backups in bedrooms and outside of sleeping area		rs permane	ently wir	ed into a recepta	acle boxes with
	Bid Cost:		х		
		Base		Quantity	Total Cost
Combination CO / Smoke Detector Hard Wired				GENERAL RI	EQUIREMENER Serior
Install a hard wired combination carbon monoxide and sm	oke detector with ba	attery back	up. (35	09)	
	Bid Cost:		_x	=	
		Base		Quantity	Total Cost
Light Fixture Replace				BATHROOM-	MASTER
Replace or install a ceiling mounted 2 bulb or wall mounte	d 4 bulb strip, UL a _l	oproved, CF	L or LE	D light fixture w	ith shade and lamps.
	Rid Cost		x	=	
	Dia 0031	Base		Quantity	Total Cost
GFCI Receptacle 20 AMP				BATHROOM-	MASTER
Install a flush mounted, ground fault circuit interrupted, du	olex receptacle and	cover plate	. Fish v		
	Bid Cost:		x	===	
		Base		Quantity	Total Cost
Replace - Switch Plate & Switch				BATHROOM-	MASTER
Install a single pole switch and cover plate.					
	Bid Cost:		_x	=	
		Base		Quantity	Total Cost
GFCI Receptacle 20 AMP				KITCHEN	
Install a flush mounted, ground fault circuit interrupted, du	olex receptacle and	cover plate	. Fish v	vire and repair al	I tear out as needed.
	Bid Cost:		х	=	
	<u> </u>	Base	<u> </u>	Quantity	Total Cost

Ceiling Fan with Light Kit

KITCHEN

Install a 52" 3 speed flush mounted ceiling fan with a minimum two bulb UL approved, CFL or LED light fixture with shade and lamps. Include ceiling fan mounting box. (35.10)

	Bid Cost:	x	=	
		Base	Quantity	Total Cost
Repair Category: 11.0 Plumbing & Fixtures		the time of the consequence of the production of		
Description		Floor	Room	<u>Exterior</u>
Water heater 40 Gallon Gas			GENERAL R	EQUIREME NE Kerior
Remove existing water heater and all obsolete or deterior	rated flue piping and	gas line and dispo	se of properly.	
Install an insulated 40 gallon, glass lined, high recovery g greater.	as water heater with	ı a 10 year warrant	y and an Energy	Factor of .61 or
Installation includes PRV valve and extension, drain pan through the roof as necessary to meet the requirements of				
	Bid Cost: _	x	=	
		Base	Quantity	Total Cost
17" Height Commode Replace			BATHROOM-	MASTER
Install a 17" height, 2 piece, close coupled, white, vitreous Include plastic or pressed wood white seat, supply pipe, s			er usage per flus	sh of 1.6 gallons.
	Bid Cost:	х	=	
	<u></u>	Base	Quantity	Total Cost

Bathtub and Shower Surround 5' Fiberglass

BATHROOM- MASTER

Install a 5', white Swan or equivalent 3 piece, fiberglass shower surround. Caulking all seams and penetrations. Include new single handled tub/ shower diverter valve and drain.

TOTAL CONTRACTOR CONTRACTOR	-	en	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		300	
\$15,1500ACR030B0	200238		100
7-1,352,799,388,88	1000000		
The second second	50000000		
\$2.965.00000000000000000000000000000000000	6.88639888		
100000000000000000000000000000000000000	20 BOOK -	The second second	
1457-050000000000000000000000000000000000	03000000		
-2512022238	S200 NORMS - 3		
DATE: STATE OF STATE	SEC. 1889 - 1		100
\$200 PM (Sept. 1988)	10,000,000		10 C
107/12/2015 (0.00)	2000 200		100
2007/06/00/2004	70 KB 10		
Consultation of the Consul	10000000	1000	200
2017 CO. S. C. S.	100000000		
50.00 Silvano A. Carlo	00000000		
2002		A 100 Car 100	860.47
25/19/19/09/2005	3500000		8333
200000000000000000000000000000000000000			
6526			
\$100 at 100 at 1			13-56
\$2000000000000000000000000000000000000	100		15.00 (200)
100000000000000000000000000000000000000	50000		100
Sec. 200	100 Sec. 1800		
The second second	78. SA		
\$5.500 KB-2			30 XXXX
200 m		\$35 AT \$35 AT \$3	
2200	100 miles		
2000 4 7 19	March - Walle	The second second	2.003(0)
7.00	2000		
27 Con 12 to	200000	200000000000000000000000000000000000000	
100000000000000000000000000000000000000	CONTRACTOR OF THE	30000000000000000000000000000000000000	
		10000000	

Bid Cost: _		X=	
	Base	Quantity	Total Cost

Double Bowl Sink Complete

KITCHEN

Install a 18 gauge 33" x 22" x 9" double bowl, stainless steel, self rimming kitchen sink including a single handle metal body faucet, rated at 2.0 GPM or less, with a 15 year drip- free warranty, P-trap, supply lines, full port ball type shut-off valves & escutcheon plates on all supply & drain lines. No copper compression fittings.



Bid Cost: _		X=	=
	Base	Quantity	Total Cost

Waste-Line Snake

GENERAL REQUIREMENT Serior

Power snake 3 baths & kitchen drains to clear lines for fixtures to main street sewer

Bid Cost:	X		
	Base	Quantity	Total Cost

Repair Category: 12.0 Floor

<u>Description</u>

Floor Room

Exterior

Floor System Repair

BATHROOM- MASTER

Remove all fixtures not built in. Dispose of floor assembly. Install 2"x 10" joists hung 16" on center, 3/4" subfloor. Include replacing all deteriorated band joists and insulating floor to code.

Bid Cost: X = Total Cost

Resilient Flooring

BATHROOM- MASTER

Install 25 year warrantied resilient floor covering per manufacturer's specifications. Include transitions and painted or stained wood quarter-round at all perimeters to complete installation.

	100 miles	E-12	
		144500000	
- CESS.	9833846	E965/89/	
45335		7 - 10 mm	
		Sec. 1985	
	2000000	20 EU 2	
(A) (1) (A)	Bar	2000	
Service Control		200	
2.50 March 1995	F 34 (3.989)	75 2000	
000000000000000000000000000000000000000		100	
		2,000	
200 C	and the being a	100	
50 St. 10		4.53	
\$25 Cont. 10	100 Day 07	286	
23000		8.78	
12 CO	A 100 M	200	
\$50000 TO 1000	Na Y	224	
5.350,000,000		Contract of the Contract of th	
200			Siction
N. S.			2002000
	5000		SEC. 1
200000000000000000000000000000000000000	200000-0467	San San San	BOROS 1
200			Sec. 10
697		965,039	20000000
38	Sec. 2002	198,438	200000
35 35	4.55 G/2	1000000	000000000000000000000000000000000000000
S 80	September 1	5000	
A 25	3000000	. 400	and the same
2 Alban			A
2010004000	4000	2888	
200 march 200 mg	Acceptance	2000 · · · ·	
200802000000000000000000000000000000000	ASSESSED NO.	2000	
AND DESCRIPTION OF THE PARTY OF	All Sales	10000	
	ACCOUNT OF	15.778953	

Bid Cost:		X	
	Base	Quantity	Total Cost

Floor System Repair

KITCHEN

Remove all fixtures not built in. Dispose of decayed floor assembly only . Install 2"x 10" joists hung 16" on center, 3/4" subfloor where required. Include replacing all deteriorated band joists and insulating kitchen floor to code.

	Bid Cost:	x		=
	I	Base	Quantity	Total Cost
Resilient Flooring			KITCHEN	I
	installation.			ainted or stained woo
	installation. Bid Cost:	s. Include tra X Base		ainted or stained woo = Total Cost
Install 25 year warrantied resilient floor coverus to complete quarter-round at all perimeters to complete	installation. Bid Cost:	x		=

Repair Category: 13.0 Interior Wall & Trim

- ----

Description

Floor Room

Exterior

Prep & Paint Room Semi Gloss BATHROOM- MASTER

Remove or cover hardware and accessories not to be painted. Scrape loose, peeling, cracked and blistered areas. Clean oil, grease, fungus, dirt, and dust from surfaces. Fill holes and cracks. Prime all new materials and spot prime existing with acrylic latex. Top coat with owner's choice of low VOC acrylic SEMI-GLOSS latex. Replace or uncover hardware, fixtures and accessories. Any moving of furniture required shall be included. (33.27)

Bid Cost:		X=_		
	Base	Quantity	Total Cost	

KITCHEN

Repair wall finish. Patch drywall or plaster holes in wall greater than one inch. All others use an adhesive mesh and mud over the mesh with the appropriate material. Wet sand smooth. (Also 26.0 - Plaster)

	Bid Cost:		x	=
		Base	Quantity	Total Cost
Prep & Paint Room Semi Gloss			KITCHE	N / DINNING ROOM
Remove or cover hardware and accessories not to be painted fungus, dirt, and dust from surfaces. Fill holes and cracks. Prir with owner's choice of low VOC acrylic SEMI-GLOSS latex. Refurniture required shall be included. (33.27)	ne all new mate	erials and spot	t prime existing	with acrylic latex. Top coat
MATERIAL STATES	Bid Cost:		x	=
	_	Base	Quantity	Total Cost
Wallpaper Removal -Kitchen / Dinning Room / Mast.Bath		Industria di Sa	KITCHE	
Remove existing wallpaper to a clean wall surface ready for pr compound sanded and smoothed if needed.	imer and paint.	include a thin	skim coating of	r ligntweight joint
	Bid Cost:		x	=
		Base	Quantity	Total Cost
Drywall Entire Room - Master Bathroom				
Remove all gypsum, paneling, lathe and plaster or miscellaned code. Glue, nail and screw new drywall. Apply tape and 3 coat paint. (Also 26.0 - Plaster)				
	Pid Coots		Y	

Base

Quantity

Total Cost

Repair Category: 15.0 Insulation **Description** <u>Floor</u> **Exterior** Room Insulate Floor R-19 FOUNDATION/CRAWL SPAGFor Install R-19 Kraft faced batt fiberglass insulation to floor where missing. Vapor barrier must face heated space. Use strong wire, "tiger teeth" or mesh to hold insulation in place. (24.3) Repair Category: 16.0 Cabinets, Accessories & Appliances **Description** Floor Room **Exterior** Vanity/ Counter Top/ Sink/ Mirror Replace Complete **BATHROOM- MASTER** Install new vanity cabinet complete with counter top of laminate with vitreous china sink or marble-lite top with preformed sink. Include single handled metal faucet with drain and pop-up, P- trap, supply lines, full port ball type shut-off valves & escutcheon plates. **Total Cost** Quantity **Grab Bars BATHROOM- MASTER** Install 1 1/2" diameter S/S Grab Bars on 3 walls at height of 36" (include wood blocking in wall. Each bar must hold 300 pounds). Owners choice of locations. (38.1) Accessory Set - 3 Piece Chrome **BATHROOM- MASTER** Install a chrome plated steel bathroom accessory set consisting of a 24" towel bar, hand towel ring, and toilet paper holder.

Total Cost

Cabinets Wall KITCHEN

Replace wall cabinets. Cabinets are to be constructed of solid maple and plywood. No particle board allowed. See contractor's manual guidelines & specifications for full requirements.

- 14 Jan-19	Bid Cost:	x_	=	
		Base	Quantity	Total Cost
Cabinets Base			KITCHEN	
Replace base cabinets. Cabinets to be constructed guidelines & specifications for full requirements.	of solid maple and plywoo	d. No particle boa	ard allowed. See	contractor's manual
	Bid Cost:		=_	
		Base	Quantity	Total Cost
Counter Tops Replace		KITCHEN		
Screw to base cabinet a square edged plastic lamin adjoining walls with low VOC caulking to match wall				k counter top to
	Bid Cost:	Х		
		Base	Quantity	Total Cost
Repair Category: 17.0 Stairs & Steps				
Description		Floor	Room	<u>Exterior</u>
Exterior Handrails (Decayed Wood)			STAIRS & ST	EPS
Remove any decayed wood, replace, paint two coa	ts matching low VOC pain	t.		
	Bid Cost:		=	
		Base	Quantity	Total Cost

Certification

Contractor Name:	Total Cost:
Signature:	Date: